

TABLE 7 Cases with Reported Tank Testing Results

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
01 SAN LEANDRO	T	38	TC		9/9/94	P		0.0475,0.046,0.022 P test & 0 .11,0.22,0.04 U test, hole on top. Test results showed they are tight, but there was evidence that they had leaked. Removed tanks were corroded & hole on top.
05 SAN ANDRES	U	29	TC	7/11/95	7/20/92	P	36	4/12/90 Ainlay tank test
05 ANGELS CAMP	U	24	TC	2/23/95	6/15/94	P	8	4/3/92, 6/15/93 Horner test method
08 HIOUCHI		U	TC		6/25/91	P		6/10/87 Ainlay test

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
09 MEYERS	O	32	NC	2/13/96	2/28/92	P	48	AutoShut off failure
09 PLACERVILLE	U	19	TC	11/3/95	12/29/94	P	11	12/19/92 Horner tank, Acurite piping. Tanks are manifolded
09 PLACERVILLE	U	13	TC	1/22/96	6/28/95	P	7	7/20/94 UST2000 U&P, 12"/48", 20"/48" - test not valid
10 FRESNO	T	33	TC	10/16/95	4/26/95	P	6	90, 92,93,94 P Horner. For 95 test : 0.039 leak rate. Tank: rusty, pitted, holes. 550 gallon tank
10 FRESNO	D	25	TC	1/19/96	12/10/91	P	49	6/23/88 P petroTite, 12/19/89 P AESII, Tank light to mild rust

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
10 FRESNO	D	6	DR	1/24/96	1/1/95	P	12	3/96 P
10 FRESNO	D	U	TC	12/22/95	3/16/94	P	21	89, 90, 91, 92 P. 3/11/93 two tanks F, 3/25/93 two tanks F, 4/2/93 P Tel-A-Leak.
10 FRESNO	T	U	SB	12/4/95	3/24/94	P	21	90 P, NDE test method. 93 P TelALeak.
10 FRESNO	D	U	TC	10/18/95	3/1/94	P	19	tank mild rust, no holes
10 ORANGE COVE	TD	U	TC	2/2/96	6/1/92	P	44	Holes on bottom of tank. 12/90 MIR summary P

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
10 SANGER	D	U	TC	10/20/95	5/5/94	P	17	No ullage test, tanks @ 70"/96" (0.0268 gain) and 73"/96" (0.01229 loss)
10 FRESNO	TL	U	TC	12/22/95	3/16/94	P	21	5/21/92 & 8/13/93 two tanks P and two tanks F the VacuTect test. 1/25/94, 4/7/94 P but no line or LLD tests.
10 REEDLEY	D	20	PS	10/3/95	10/14/95	P	0	10/23/91 P TEI, 9/10/92 P TEI4000, 10/10/94 P UST2000 tank and CampoMiller
10 FRESNO	S	U		10/30/95	11/16/95	P	-1	11/16/94UST2000 No LLD, aboveground lines. 11/5/91 fail, 11/19/91& 11/26/91 P (NDE VPLT). Leak: AUST spill
10 FRESNO	DL	13	TC	11/2/95	4/14/89	P	79	station closed prior to 91. Holes noted on one tank

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
11 ORLAND	U	U	SA	6/3/94	1/1/88	P	77	Property transfer. Tanks in good condition. Suspected leak source was tanks removed in 1989. 87/88 tests Pass
15 TEHACHAPI	U	15	TC	1/5/96	9/16/94	P	16	tanks removed in 11/95. 12/92 annual maintenance check inidcates presence of tank level monitors. 12/20/93 UST 2000P&U pass.
15 BAKERSFIELD	P		PT	10/24/95	10/23/95	P	0	Loose union found during annual test (UNL). 10/21/93 tank, pipe, MLD test. Three SIR fails during 94 for each tank (SIRAS). These are attributed to dip stick error. 9/95 and10/95 SIRAS- tight tanks
15 BAKERSFIELD	DO		TC	9/26/95	2/10/94	P	19	Some excess MIR variations reported. Tanks in good condition. overfill and filter change seem as source.
15 SHAFTER	U	17	TR	1/26/96	2/24/94	P	23	USTMAN 93 results P with June (1 T) and August (2 Ts) Inconclusives(?). 12/8/93, 2/25/94 Tanknology test pass tank MLD, and lines. 4/17/95 SIR pass

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
15 LAKE ISABELLA	U	9 DW	SA	1/19/96	2/6/96	PF	-1	test 2/96: T2 F @ 112" & P @ 96" (tank D=96"). report: T1- Loose cap on level probe riser, T2 - Leak about 98" near manway, T3 leak at Union on turbine connection flex hose product line.
15 EDWARDS AFB	U	34	TC	1/9/95	12/1/93	P	13	
17 KELSEYVILLE	T	36	TC	12/6/95	3/31/93	P	33	2/94, 8/94, 9/94 gains exceeding SIR threshold on one tank were reported "P". SIR method used not reported. 3/31/93 UL Reg Line test , and XLD passed. 7/1/94 both Reg & Sup UL lines and XLDs pass.
19 AZUSA	U	27	TT	3/30/95	5/16/94	F	10	One ULT failed 87 & 88 TT. 87- 94 other ULT (5/16/94 VacuTec) and Woil (9/27/94 PetroTite) passed. 4/19/93 VacutecT&P pass but Water in two tanks (1.57" Plus U& 4.5" Woil). ELD present.

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
19 ROLLING HILLS ESTAT	U	28 S	OT	11/28/95	7/6/94	P	16	Waste oil tank. leak discovered by 94 site investigation.
19 ALHAMBRA	T	U	SI	3/6/91	1/28/87	P	50	1988 Site Investigation discovered leak. waste oil tested on 3/12/87 "P".
19 WHITTIER	U	26	TC	11/7/95	10/26/92	F	37	Tank removed 10/31/95. 86,88,90,11/14/91, 12/7/91 and 12/14/93 (NDE) tests on gasoline and waste oil tank. 10/26/92 "Fail" tank test on unleaded gasoline tank .
19 COVINA	U	18	TR	10/31/95	6/12/90	P	64	
19 SOUTH GATE	U	U	TC	12/11/95	3/3/92	P	45	Diesel tank removed 10/10/95. 86, 88, 89, 90 and 3/3/92 tests P.

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
19 SHERMAN OAKS	P	U	IC	1/3/96	1/3/96	P	0	
19 CARSON	U	29	TC	12/11/95	2/23/92	P	46	86,88,89,90,92 tests all pass.
19 SANTA MONICA	U				2/6/95	P		550 gallon diesel tank. Tester did not certify the tank as a DW tank, because there was a common vent line between the tank and annular space.
19 MONTEBELLO	U	38	TC	12/11/95	9/30/94	P	15	Diesel tank removed 10/17/95. tank tests 9/2/87 and 9/30/94
19 ROSEMEAD	U	20	TC	7/1/88	3/31/90	P	-20	Diesel tank removed 8/11/95.

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
19 SAN GABRIEL	U	16	TC	12/12/95	12/28/88	P	84	Diesel tank removed 9/12/95. 8/28/86, 8/28/87, 12/28/88 tests Pass.
19 NORWALK	U	U	SA	4/1/94	10/21/93	P	6	Tank tests 3/26/86, 11/21/9, 10/21/93. Unleaded gas and diesel contamination.
19 LAWNGDALE	P	19	IC	11/16/95	6/1/87	P	101	1995 MIR discrepancy lead to leak discovery.
19 SOUTH PASADENA	U	20	TC	12/19/95	7/7/94	P	17	86,88,90,91,92,7/7/94 tests pass. 8/24/95 tank closed in place
19 HUNTINGTON PARK	U	32	TC	12/19/95	8/23/93	P	28	Gasoline tank removed 5/4/94. 87,88,90,91,4/15/92,5/26/92, and 8/23/93 tests all pass.

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
19 LOMITA	U	38	TC	12/11/95	2/22/92	P	46	6/17/86, 8/23/88, 8/31/89, 8/12/90 tightness tests. Diesel tank removed 10/19/95. Dispenser contamination discovered during tank removal.
19 INGLEWOOD	TD	29	TC	11/2/95	11/13/94	P	12	Tank removal date 7/11/95. Waste oil and gasoline tanks. No line leak detectors. Woil Leak rate 0.045 gph.
19 BALDWIN PARK		11			1/30/94	P		No contamination confirmed. 88-92 & 1/30/94 tank /piping//MLD tests, all Pass. All Monitors checked in 94 & 4/24/95
19 WHITTIER	U	13 F	AI	11/19/93	11/22/94	P	-12	88,89,91,11/22/94 tests pass. 12/8/93 Ronan checked. 11/11/95 , 1/29/96 PetrosonicIII, red Jacket PPM4000 checked. 93 leak detection investigation led to discovery.
19 SOUTH EL MONTE	T	21	TC	9/21/95	10/15/93	P	23	Unleaded gasoline tank removed 9/21/95. 86,87,88,89, (these reports suspected of being falsified), 92 and 10/15/93 tests pass.

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
19 COMPTON	TLD	16	TC	6/4/91	3/19/86	p	63	5 tanks 16- 27 years old, one is a clarifier tank, never tested. Failed gasoline tank P the 3/19/86 tank test. Diesel tank "P" a 10/16/85 test, no line test, leak was around pipe and dispenser.
19 SANTA MONICA	U	DW	TC	2/20/96	2/6/95	P	12	550 gallon tank. Manual TG readings from 7/93-8/95, all the before and after reading are exactly the same, recorded to 1/4". Tester found sensor, non-operational. leaky daytank. tester closed valve.
19 WESTCHESTER	U	5	OT	2/28/96	11/1/91	P	51	City of Los Angeles jurisdiction
19 LA MIRADA	U	38 F	SW	10/26/95	11/15/94	P	11	waste oil tank. removed 10/17/95. 12/22/88, 5/6/89, 12/13/89, 10/6/91, 11/9/93 (NDE) tests all pass. leak discovered during line and dispenser replacement. ELLDs present.
19 POMONA	U	U	TC	1/25/96	11/14/91	P	50	8/15/86 test pass. Unleaded gasoline tank removed 11/1/95.

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
19 ROSEMEAD	P	U	TC	11/1/95	8/31/92	P	39	Gasoline tank removed 9/13/95.
19 DOWNEY	U	12	TC	6/14/91	8/14/87	P	46	tank removal 5/30/91
19 INDUSTRY	T	21	TC	12/28/95	8/23/93	P	28	Diesel tank removed 11/7/95. 10/11/89, 3/5/91, 8/23/93 tests all pass
19 OLIVE VIEW	U	U	TT	12/13/95	7/28/95	F	5	Tank removed 11/3/95. Piping test inconclusive because the foot valve not holding pressure.
19 GARDENA	U	U	TT	3/1/94	1/8/93	P	14	Pass tank tests on 2/86, 5/89, 3/18/93, 3/17/94. Tank & lines passed 2/8/96 NDE test. 1/8/93 tank test F(tank,vent & vapor lines), 1/16/93 F (ullage, vent & vapor).

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
20 CHOWCHILLA	U	U	TC	6/22/95	10/16/92	P	32	one tank failed tightness test)Petrotite) on 2/1/87.Tank was placed under temporary closure on 8/12/87. Tank was tested in 1992 (NDE) and passed. Most of contamination was under the dispenser.
20 OAKHURST	U	18	TR	11/13/95	7/14/94	P	16	MIR summaries 1/90,10/91,1/92,4/92,7/92,10/92,3/94,2/95. No holes observed in tank.
20 MADERA	T	U	TC	7/19/93	6/1/91	P	25	MIR summaries for 1/90,10/90,1/92,4/92,7/92,10/15/92. Tank removed 6/25/93. Small holes obsereved in the tank.
23 HOPLAND		U	TT		2/9/93	F		2/93F(leak rate).124gph. tester recommended exposing tank top, isolate plumbing to do a tank only test. 2/6/92 pass (0.043 gph).some weekly water readings on Woil, 7"water noted on 88 inspection.
23 REDWOOD VALLEY		U	TR		5/11/94	P		3 tanks,rusted. Tank 1 not placed in bed of sand, had hole along the bottom, almost opposite suction pipe. Test leak rate 0.043. Tanks tested tightt 6/3/92. Full system test. Not all tanks tested.

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
23 ALBION	S	U	UP	9/27/95	9/30/95	P	0	9/30/95 (0.045gph for one of the manifolded tanks) . tanks tested as one on 9/9/94, P. Excavato in prior to lining lead to leak discovery (appeared to be due to overfill)). tanks determined sound.
23 ELK		U	AI		6/15/95	P		tightness test 6/95 one tank 0.0395gph, T1&2 tested together. 6/7/94 tank 1&2 tested together (0.0305gph) and 3 &4 tvent manf. 1/26/96 inspection: MIR records available, May 95 records indicate leak.
28 NAPA	U	40	TC	10/30/95	10/6/95	P	0	Tank tested tight three times in five months. Numerous holes discovered in tank at the time of removal. 4/10/95 NDE (Alert 1000,1050, Acurite, all pass, MLD fail). 8/26/95 NDE (VPLT,UTS4T,PTK88)
28 AMERICAN CANYON	U	U	SI	10/12/95	7/19/94	P	15	Annual SIR for 1995: gains in excess of threshold reported as passes. Tank 1: months 1,4,7,8; Tank 2: months 6,7,9,10; Tank 3: months 4,8,9,10 (4.86gph!). SIRAS. water at site is above tank bottoms.

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
29 TRUCKEE, CA	U	U	UP	1/30/96	4/29/94	P	21	Leak discovered during assessment for TL. 5/95 gain (0.23 gph) reported as pass. 12/95 fail reported for two tanks (MDL, CLR listed as N/A).4/95-5/96 SIRAS. 1/96 data one tank CLR=LTH.
29 GRASS VALLEY	U	U	TT	12/10/95	12/10/95	F	0	6 tanks. 3/14/95 P tank (Ainlay) & lines(?).12/10/95 test: UST2000P pass tanks 1-4, tanks not full; PetroTite line test pass, LD Pass; Horner EZy test 5 &6, 6 fail, Diesel suction line F.
29 GRASS VALLEY	U	U	SA	9/11/95	7/7/95	P	2	2/8/95 Horizon (tracer) test pass tank, pipe, LD, no sampling points around piping.12/94-4/95 USTMAN SIR pass. No ullage test data provided.
30 FULLERTON	U		TC	8/10/95	5/26/95	P	3	Tanks P 7/92,3/93,9/94 test.Sensors failed 3/16/95 certification. Tank Guard sensor monitors Diesel turbine sump. 93 & 95 NDE test P LD and tank and pipe.
30 ANAHEIM	P	10	UP	10/31/95	8/16/95	P	2	Leak discovered during upgradeing.

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
30 COSTA MESA		10+	TC	10/25/95	1/13/95	P	9	SIR International: 1/94-12/94 no loss reported (0.038-.097gph), some Incon on different tanks (.286-.528). 95 results no loss (.033-.17). 1 Manifold: no data 11/95,12/95. 8/95 significant loss(0.486)
30 FULLERTON	P		LD	2/17/96	5/19/95	P	9	Leak discovered (in turbine flex connector) by MLD going into slow flow and inventory loss of 3000 gallons. ELD was apparently disabled. 5/92-6/96 annual tank tests all pass.
30 STANTON		28	TR	11/9/95	3/10/94	P	20	TEI ullage was also conducted on all tanks, vent and vapor lines, all passed. Check valve on tank#2 would not hold, so no test result reported.
30 WESTMINSTER		8	TR	1/22/96	10/1/91	P	51	
30 SANTA ANA			TT		6/22/95	F		6/22/95 three tanks passed but one of the 550 gal oil tanks failed the system test and line test. Tank was taken out of service and Avis requested a temporary closure permit.

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
30 WESTMINSTER				1/4/96		P		
30 ANAHEIM		6			10/1/89	P		leak reported as pre-existing by the agency.
30 STANTON		17	TR	9/27/95	5/1/94	P	16	1/94-9/95 USTMAN SIR results all tight. Inconclusive on one tank (9/95) and pass the other tank.
30 HUNTINGTON BEACH		7	TC	1/23/96	10/1/94	P	15	
30 SANTA ANA		40	TC	12/12/95	5/17/95	P	7	Permit application for this test is included with info agency sent us but no test report/result is included.

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
30 ANAHEIM		23	TC	9/12/95	9/9/95	P	0	Tank passed the test with a leak rate of 0.047.
30 LA HABRA		13	TR	11/28/95	6/28/95	P	5	
30 SANTA ANA		22	TC	7/19/94	1/11/91	P	42	89 petrotite test:P. permit for testing 5/18/92 provided by the agency, but no test result reported.
30 SANTA ANA		17	WS	6/2/95	6/24/92	P	36	Leak discovered by water samples. 2/90 petrotite test pass.
30 PLACENTIA		21	TR	8/24/95	1/1/90	P	67	

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
30 BUENA PARK		15	TR	8/18/95	7/1/91	P	49	SIR reports for 10/93,11/93, Warren Rogers: Pass. Annual IR summary indicates all variations for 93 within allowable range.
30 BREA		16	TR	9/13/95	7/1/93	P	26	
30 BREA		U	TR	7/1/95	1/1/90	P	66	
30 BREA		15	TR	10/1/95	7/1/91	P	51	
30 SANTA ANA		12	TR	10/18/95	6/10/93	P	28	91 & 92 test results indicate testing using Horner. Agency has sent us tank test permits from 87-90 but not test results.

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
30 SANTA ANA		22	TR	6/22/95	8/3/93	P	22	6/11/92 test by the same company pass. One waste oil tank onsite.
30 SANTA ANA		12	UP	9/26/95	3/23/95	P	6	Tank, pipe, & LD passed tests 3/95, 5/94 by NDE. 9/3/89 NDE full system passed all tanks. 10/20/89 full system NDE test failed 12K UNL(87) @ o.1gph. 1/92 TEI test passed all.
30 WESTMINSTER		10	PW	9/12/95	9/29/94	P	12	Leak discovered during piping work. 1/94-12/95 summaries do not report a loss (0.022-0.097gph). 10/94 inconclusive reported as a possible chart error (0.525gph). Same tank6/95 loss of 0.401gph.
30 COSTA MESA		10+	TR	12/6/95	5/9/94	P	19	
31 AUBURN	P	18	TC	9/29/95	9/20/92	P	36	

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
31 COLFAX	U	23	TC	10/31/95	4/3/92	P	42	12/90, 3/91, 3/92, 9/92 tightness testing reported all tanks tight. No line test results.
31 ROCKLIN	U	31	TC	11/13/95	3/12/92	P	44	
32 QUINCY	OL	20	TC	10/13/95	1/11/95	P	9	Source of leak was overfill and line leakage. 95 tank tested as 2000 gal, when removed discovered to be 3000 gals.
34 HERALD	U	17	TC	6/21/93	7/8/91	P	23	

* Time lapsed between last tank test and leak discovery date (months)

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
34 NORTH HIGHLANDS	U	35	TC	12/5/95	5/8/92	P	43	
41 SAN MATEO	U	U	TC	11/9/95	6/28/94	P	17	tanks have been tested tight since 1986. 3 tanks on site. Tests: 87 Leak Lokator, 88 AESII, 88 VPLT, 89 & 90 PetroTite?, 91 AES, 93 NDE.
43 CAMPBELL	U	U	TC		5/27/93	P		No signs of leak or holes were found on the tank. No leak rate reported for line test, "INC" included in that information area.
49 HEALDSBURG		40+	TR	2/12/96	1/18/95	P	13	(SIRAS 2.8.3). 3/95-5/95 SIR analysis. 3/95 pass, 5/95 not enough data to analyze. 3 tanks on site.

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
49 SANTA ROSA		19	TC		2/1/94	P		Site was very contaminated. 87 PetroTite P, 86 & 88 & 89 (EZYCheck) P, 93
49 SANTA ROSA		104	TR		9/29/94	P		94 tanks passed with 0.0222, 0.0315 & 0.0434 gph. 91, 92, 93 tests by same company pass. 90 test by same tester fails waste oil @ 0.1292 gph loss. No followup info.
52 RED BLUFF	U	21	TC	1/22/96	8/31/95	P	5	3 tanks on site. 2/17/92 PetroTite test failed one tank @ 0.684gph. 4/8/92 same tank passed @ 0.002 gph. 1/23/93 Pass. 1/13/94 Ainlay test pass. No report on 92 fail test followup.
52 PASKENTA	U	14, 33	TC	1/22/96	5/18/92	F	44	10/31/86 AES test failed 1000 gal suction pipe. repaired. 5/18/92 test : 550 gal tank failed @ 0.245gph. system pass test on 6/5/92 by same tester after repair. 3/27/91NDE test 550 gal, P.
52 LOS MOLINOS	U	36	TC	12/21/95	5/14/91	P	55	Tanks put on temporary closure2/9/94. Application for removal submitted 1/16/96.

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
52 RED BLUFF	U	23	TC	11/3/95	12/19/94	P	11	3 tanks on site.12/90, 11/91, 11/92 , 11/93 PetroTite tests pass all tanks. MIR 10/7/91 quarterly report all fail, all 92 & 93 MIR fail, the annual report of this submitted in March 95
52 MINERAL	U	7, 13	TC	10/27/95	11/5/92	P	35	Tested tanks also in 1991, P.
54 LINDSAY	U	28	TC	12/14/95	4/20/95	P	8	2/9/94 tanks also tested tight by Tanknology
54 EARLIMART	U	11DW	PS	9/7/95	11/19/95	P	-2	3/26/94 Tanknology tested tanks
54 PIXELY	P	U	TC	10/13/95	12/16/94	P	10	12/94 tests product levels: 71/96, 70/96, 68/95. one of the lines pass @ -.0405gph. 2/6/94 test tank @ 61, 64, 72/96", all pass.

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
54 VISALIA	U	17	TC	10/6/95	9/7/94	P	13	No pipeline leak detectors. 9/16/93 tests pass
54 TRAVER	U	13	PS	10/4/95	8/22/95	P	2	Previously undisclosed additional UST discovered during property transaction assessment. Tanks @ 71/96, 73/96, 73/96".
54 WOODLAKE	U	U	PS	9/20/95	2/27/94	P	19	4/12/96 agency notification letter to tank owner to appear for failure to test tanks. 2/27/93 line test is questionable, tanks pass, no ullage test. 2/94 test product level 31/48"
54 DINUBA	P	U	PS	2/5/96	12/16/95	P	2	1/18/95 UST2000P&U test pass all three tanks (product level 56, 65, 57 for 74"D tank), piping test PL400 pass. 12/16/95 product level (69/75, 69/96, 56/75). Same tanks different diameters.
55 GROVELAND	T	U	TC	1/2/96	11/17/93	P	26	The business was closed for business some time after 12/23/93. Tanks were pulled in 1/2/96. 11/10/92 test pass @ 0.045, 0.020 gph, Ainlay.

County/ City	Leak Source	Tank Age	How Discovered	Date Discovered	Last Tank Test	Result of Tank Test	Time Lapse*	Notes
57 GUINDA	T	U	TC	7/20/95	1/1/93	P	30	Source of leak was an unknown tank near permitted one.

121 - Total of cases with available tank test results							Average time, in month, between last tank test and leak discovery	24.3
							Number of cases where tank testing discovered the leak:	6
							Number of cases with tank as the leak source:	14